

Volume 12
Fractography

1. Fractography: Principles and Practices

History of Fractography
Modes of Fracture
Preparation and Preservation of Fracture Specimens
Photography of Fractured Parts and Fracture Surfaces
Visual Examination and Light Microscopy
Scanning Electron Microscopy
Transmission Electron Microscopy
Quantitative Fractography
Fractal Analysis of Fracture Surfaces

2. Atlas of Fractographs

Introduction: Atlas of Fractographs
Pure Irons: Atlas of Fractographs
Gray Irons: Atlas of Fractographs
Ductile Irons: Atlas of Fractographs
Malleable Irons/White Irons: Atlas of Fractographs
Low-Carbon Steels: Atlas of Fractographs
Medium-Carbon Steels: Atlas of Fractographs
High-Carbon Steels: Atlas of Fractographs
AISI/SAE Alloy Steels: Atlas of Fractographs
ASTM/ASME Alloy Steels: Atlas of Fractographs
Austenitic Stainless Steels: Atlas of Fractographs
Martensitic Stainless Steels: Atlas of Fractographs
Precipitation-Hardening Stainless Steels: Atlas of Fractographs
Tool Steels: Atlas of Fractographs
Maraging Steels: Atlas of Fractographs
Iron-Base Superalloys: Atlas of Fractographs
Nickel-Base Superalloys: Atlas of Fractographs
Nickel Alloys: Atlas of Fractographs
Cobalt Alloys: Atlas of Fractographs
Copper Alloys: Atlas of Fractographs
Cast Aluminum Alloys: Atlas of Fractographs
Wrought Aluminum Alloys: Atlas of Fractographs
P/M Aluminum Alloys: Atlas of Fractographs

Titanium Alloys: Atlas of Fractographs
Miscellaneous Metals and Alloys: Atlas of Fractographs
Metal-Matrix Composites: Atlas of Fractographs
Cemented Carbides: Atlas of Fractographs
Ceramics: Atlas of Fractographs
Concrete and Asphalt: Atlas of Fractographs
Resin-Matrix Composites: Atlas of Fractographs
Polymers: Atlas of Fractographs
Electronic Materials: Atlas of Fractographs